
C-7000 Firmware Version

Firmware version number can be checked in "Product Information" in "Setting" in C-7000

Main & Sub Program	n
--------------------	---



Date	Main No.	Sub No.	Contents
2015/3/12	10	10	Mass production version
			Additional functions and bug fixing
			1) Improve the sensitivity of LCD touch panel
			2) Change the condition when dark calibration is required (to
			3) Dark calibration can be made by rotating Light Selection F
			4) Change the color of letter for unit when numeric letter is in
			5) Add QWERTY keyboard for input screen
			6) Integrate Memory Recall, Rename and Delete into "Memo
			7) Add the pop-up message when memory is stored (when p
			8) Last measurement can be memorized after the power OF
			9) Memory title is displayed in memory recall mode.
	20		10) More grid line in Spectrum Graph 11) Add Exposure time setting in Measuring Screen of ambi
2015/8/12			12) Add the function of measurement for Photosynthetic Pho
			13) Under 5lx of illuminance, Chromaticity coordinate (x,y,u',
			14) Change the display range of delta uv from +/-0.3 to +/-0.
			15) Display KC regulation mark in the meter of "Setting" page
			16) Language to display in the meter is fixed: Change can be
			17) The bug is fixed that both Range L and H icon on the sta
			the Light Selection Ring fast.
			18) The fault is fixed that readings between Cord Flash Mod
			The bug is fixed that the position of cursur on confirmation
			20) Illuminance measurement should be displayed on the ba
			21) Data of Over/Under is stored in memory after power ON
			22) Some small bug fixing.
2015/9/15	21		Improvements
			1) Improve the LED measurement
		11	Additional functions and bug fixing
			1) The bug is fixed that the measurement is not good when
			2) Display the warning when the batteries dye and the meter3) The bug is fixed that auto power off is activated even if pr
2016/3/14	22		ready-to measure time longer.
2010/3/14	22		4) The bug is fixed that radio flash triggering is not activated
			5) USB device request (clear feature)
			6) The bug is fixed that the firmware is overwritten to C-700
			7) Other small bugs are fixed.
2010/12/5	22		Improvements
2016/12/5	23		1) The bug is fixed that the memory recall does not work pro
2017/11/14	24		Improvements
2017/11/14	24		 The bug is fixed that the R15 is not selected in CRI mode
			Improvements
			1) Add the following measurement
			* CRI comparison
			* SSI
2019/11/8	25		* TLCI/TLMF
2010/11/0			* TM-30-18
			2) Display the preset contents in the Preset Selection screer
			 3) Add the language selection (Japanese, English and Simp 4) Add the continuous measurement in addition to single me
		4	5) Other bugs are fixed.
			Bug fixing 1) The bug that a battery shutdown occurs under specific co
2022/5/25	26		is fixed.
			2) The bug that the C-7000 stops operation under specific c
2023/4/1	27		Product name change
			1) The product name of SPECTROMASTER is changed to S

April 01, 2023

to skip unnecesary dark calibration)
Ring to CAL position
input
nory management".
pressing Memory button)
OFF and ON.
pient light.
hoto Flux Density (PPFD) J',v'), Dominant wevelength, Pe are not displayed.
0.1.
ige.
be done in factory only.
tatus bar of LCD are displayed when rotating
de and Cordless Flash Mode are different much.
tion screen in touch panel adjust ment is wrong.
pasis of 2 degree of field of view in any angle.
N.
n the batteries are dying.
er is tunred off.
pressing measuring button to make
d in Multi-Lights mode.
0 even if the device is not detected by Utility
roperly.
<u></u>
е.
en in ToolBox
plified Chinese)
neasurement
conditions during continuous measurement
conditions during dark calibration is fixed
conditions during dark calibration is fixed.
SPECTROMETER